

# ALPHA® EF-12000

High Solids, No-Clean Rosin Flux for Lead-Free & Sn-PB Wave Soldering

## DESCRIPTION

**ALPHA EF-12000** is a high-solid, rosin-bearing, no-clean, alcohol-based dulling flux. It possesses the unique attributes of superb electrical reliability and excellent solderability in both Lead-Free and Tin-Lead wave soldering processes. It complies with all major international requirements for Electromigration (EM) and Surface Insulation Resistance (SIR). In addition, **ALPHA EF-12000** is designed for best-in-class top-side hole-fill and superior resistance to micro-solderballing, connector bridging, and bridging of bottom-side SMT components including fine-pitch QFPs.

## FEATURES & BENEFITS

- Wide process window for superior performance in both lead-free and tin-lead alloys
- Excellent flux activity for defect-free soldering
- Best-in-class top-side hole-fill attributes
- High level of bridging and icicle resistance
- Superior long-term electrical reliability
- Evenly spread, uniform, non-tacky, clear residue on solder mask
- Dulling flux for reduced glare on solder joints during visual inspection
- Can be applied via spraying or foaming

## APPLICATION GUIDELINES

**PREPARATION:** In order to maintain consistent soldering performance and electrical reliability, it is important to begin the process with circuit boards and components that meet established requirements for solderability and ionic cleanliness. It is suggested that assemblers establish specifications on these items with their suppliers and that suppliers provide Certificates of Analysis with shipments and/or assemblers perform incoming inspection. A common specification for the ionic cleanliness of incoming boards and components is  $5\mu\text{g}/\text{in}^2$  ( $0.77\mu\text{g}/\text{cm}^2$ ) maximum, as measured by an ionic contamination tester.

Care should be taken in handling the circuit boards throughout the process. Boards should always be held at the edges. The use of clean, lint-free gloves is also recommended. When switching from one flux to another, the flux reservoir, flux tank and lines of the spray fluxer assembly should be purged with **ALPHA 425** Thinner. Conveyors, fingers and pallets should be cleaned periodically with DI Water, IPA or other commercial Solvent Cleaners to eliminate residues on the assembly edges.

**FLUX APPLICATION:** **ALPHA EF-12000** can be applied by spray, foam or wave application. A uniform coating of flux is essential to successful soldering. When spray fluxing, the uniformity of the coating can be visually checked by running a piece of pH sensitive paper matching the footprint of the assembly over the spray fluxer. Further process capability can be confirmed by placing pH paper above an unpopulated board to confirm that flux is reaching the top of the plated through-holes.

# ALPHA® EF-12000

High Solids, No-Clean Rosin Flux for Lead-Free & Sn-PB Wave Soldering

OPERATING PARAMETER	
Amount of Flux	220 - 390 $\mu\text{g}/\text{cm}^2$ (1400 - 2500 $\mu\text{g}/\text{in}^2$ ) of solids
Topside Preheat Temperature	90°C – 120°C (212°F – 248°F)
Conveyor Angle	6° - 7°
Conveyor Speed	1.0 – 2.0 m/min. (3.3 – 6.5 ft/min.)
Contact Time in the Solder (includes Chip Wave and Primary Wave)	2 - 6 seconds
Solder Pot Temperature	250°C – 265°C (482°F – 509°F)
<i>These are general guidelines, which have proven to yield excellent results; however, depending upon your equipment, components, and circuit boards, your optimal settings may be different. In order to optimize your process, it is recommended to perform a designed experiment, optimizing the most important variables (amount of flux applied, conveyor speed, topside preheat temperature, solder pot temperature and board orientation).</i>	

**SPECIFIC GRAVITY CONTROL:** If foam fluxing, the consistency of **ALPHA EF-12000** should be maintained by the addition of thinner to compensate for evaporation loss. It is recommended that the specific gravity @ 77°F be maintained between 0.815 and 0.825 by the addition of thinner. Only ALPHA 425 thinner should be used for this purpose to ensure consistency of flux foaming and soldering characteristics.

**RESIDUE REMOVAL:** **ALPHA EF-12000** is a no-clean flux and the residues are designed to be left on the board. However, if desired, **ALPHA EF-12000** residues can be cleaned with saponifier cleaner (for example **ALPHA 2110**) or commercial solvent cleaners.

**TOUCH-UP/REWORK:** Use of **ALPHA** Flux and **ALPHA Telecore** Series cored solder wire is recommended for hand soldering applications.

## TECHNICAL SPECIFICATIONS

Parameters	Typical Values	Parameters	Typical Values
Appearance	Clear colorless to light pinkish-amber liquid	Pounds Per Gallon	6.83
Specific Gravity @ 25°C (77°F)	0.818 ± 0.005	Flash Point (T.C.C.)	52°F (11°C)
Acid Number (mg KOH/g)	29 ± 2.0	Recommended Thinner	ALPHA 425
Solids Content, %, wt/wt	14	Shelf Life (from Date of Mfg.)	360 days
pH (5% aqueous solution)	3.2, typical	Container Size Availability	1, 5, and 55 Gal.
Dryness Test (JIS Z 3197-1999)	Pass	IPC J-STD-004 Designation	ROL1

# ALPHA® EF-12000

High Solids, No-Clean Rosin Flux for Lead-Free & Sn-PB Wave Soldering

## CORROSION & ELECTRICAL TESTING

Test Condition	Results	Test Method
IPC Copper Corrosion Test	PASS	JIS-Z-3197-1999
Water Extract Resistivity, $\Omega$	403	JIS-Z-3197-1999
Solder spread Ratio (SAC 305)	85.1%	JIS-Z-3197-1999

## JIS STANDARD SURFACE INSULATION RESISTANCE

Test	Conditions	Requirements	Results
JIS-Z-3197-1999	40°C / 90% RH / 96 Hrs	$> 1 \times 10^{11} \Omega$	$1.8 \times 10^{11} \Omega$

## JIS STANDARD ELECTROCHEMICAL MIGRATION:

Electrical and visual requirements of JIS standards: **Pass**

SIR value:  $> 1.0 \times 10^9$  ohm (@85 degC/85%RH/48VDC/1000hrs)

Migration: No evidence of electrochemical migration

## SAFETY

Consult the SDS for all safety information. The most recent version of the SDS is available from [alphaassembly.com](http://alphaassembly.com). Inhalation of the flux solvent and volatilized activator fumes, which are generated at soldering temperatures, may cause headaches, dizziness and nausea. Suitable fume extraction equipment should be used to remove the flux from the work area. An exhaust at the exit end of the wave solder machine may also be needed to completely capture the fumes. Observe precautions during handling and use. Suitable protective clothing should be worn to prevent the material from coming in contact with skin and eyes.

**ALPHA EF-12000** flux contains a highly flammable solvent with a flash point of 52°F (11°C). The flux must not be used near open flames or near non-flameproof electrical equipment.

## STORAGE

The shelf life information is valid for Alpha products in factory-sealed containers kept at recommended storage temperatures of 10°C - 43°C. However, if the flux is stored at lower temperatures from (-15°C to 5°C), it should be allowed to reach a temperature of 25°C - 30°C for 24 hours prior to use.



# ALPHA® EF-12000

High Solids, No-Clean Rosin Flux for Lead-Free & Sn-PB Wave Soldering

## CONTACT INFORMATION

To confirm this is the most recent issue, please contact Alpha Assembly Solutions

AlphaAssembly.com

<b>North America</b> 300 Atrium Drive Somerset, NJ 08873, USA 800.367.5460	<b>Europe</b> Unit 2, Genesis Business Park Albert Drive Woking, Surrey, GU21 5RW, UK 01483.758400	<b>Asia</b> 8/F., Paul Y. Centre 51 Hung To Road Kwun Tong, Kowloon, Hong Kong 852.3190.3100
---	--	--

Also read carefully warning and safety information on the Safety Data Sheet. This data sheet contains technical information required for safe and economical operation of this product. READ IT THOROUGHLY PRIOR TO PRODUCT USE. Emergency directory assistance Chemtrec 1 - 800 - 424 - 9300.

DISCLAIMER: All statements, technical information and recommendations contained herein are based on tests we believe to be reliable, but the accuracy or completeness thereof is not guaranteed. No statement or recommendation shall constitute a representation unless set forth in an agreement signed by officers of seller and manufacturer. NO WARRANTY OR MERCHANTABILITY OR WARRANTY OF FITNESS FOR A PARTICULAR PURPOSE IS MADE. The following warranty is made in lieu of such warranties and all other warranties, express, implied, or statutory. Products are warranted to be free from defects in material and workmanship at the time sold. The sole obligation of seller and manufacturer under this warranty shall be to replace any product defective at the time sold. Under no circumstances shall manufacturer or seller be liable for any loss, damage or expense, direct or consequential, arising out of the inability to use the product. Notwithstanding the foregoing, if products are supplied in response to a customer request that specifies operating parameters beyond those stated above, or if products are used under conditions exceeding said parameters, the customer by acceptance or use thereof assumes all risk of product failure and of all direct, indirect and consequential damages that may result from use of the products under conditions, and agrees to exonerate, indemnify and hold harmless MacDermid Incorporated therefrom. No suggestion for product use nor anything contained herein shall be construed as a recommendation to use any product in infringement of any patent rights, and seller and manufacturer assume no responsibility or liability for any such infringement.

® Registered Trademark of MacDermid Performance Solutions. ™ Trademark of MacDermid Performance Solutions.  
 © Platform Specialty Products Corporation and its subsidiaries 2016.